



EXPLANATION

- A zone monitoring well
- ▲ B zone monitoring well
- Groundwater monitoring well
- ⊕ Deeper zone monitoring well
- ⊞ Vapor extraction well
- Abandoned domestic well
- ⊗ UST backfill well

- Proposed remediation trench/pipe
- ▭ Proposed remediation compound



FIGURE

2

Shell-branded Service Station
2575 Corby Avenue
Santa Rosa, California



C A M B R I A

Well Location Map